

SAFETY RECALL NOTICE

PLEASE READ IMMEDIATELY

August 1, 2018

Dear ZFORCE SSV Owner:

CFMOTO Powersports Inc. has issued important **Safety Bulletin SAF-2018-02** for certain Model and Year ZFORCE SSVs, which relates to a required modification of the throttle pedal stop assembly. Our records indicate you that you own an affected vehicle.

The reason for this Notice:

CFMOTO has discovered a hazard may exist on a select number of 2018 ZFORCE 500, 800 and 1000 SSVs due to dislocation of the throttle pedal limiter bolt-to-limiter plate alignment.

CFMOTO is not aware of any instances where this has occurred, but it is possible that if the throttle pedal is aggressively pushed to the throttle limit stop point, the dislocation may cause the plate edge to deflect past the bolt end. This aggressive action may bind the plate edge on the bolt threads, which could lead to the throttle pedal not returning to the initial position even though the driver releases the pedal. You are being contacted because the Vehicle Identification Number (VIN) registered to you is listed in our warranty database as requiring modification.

CFMOTO recommends having Safety Bulletin SAF-2018-02 performed on your ZFORCE at your earliest convenience, at no cost to you.

<u>Affected Component(s)</u>	<u>Repair Action(s)</u>
Throttle Pedal Limit Bolt and Plate	1- Modify the existing pedal assembly to restore correct stop bolt to plate contact.

What you should do:

Please contact an authorized CFMOTO dealer at your earliest convenience to have your throttle pedal assembly repaired. While talking with your dealer, inquire about their schedule and how long they will need to keep your vehicle to complete the repair.

(NOTE: Per CFMOTO warranty terms and conditions, there is no consumer reimbursement policy for return of product to the dealership or for the extension of warranty.)

What CFMOTO and your Dealer will do:

Your CFMOTO dealer has been authorized and is ready to complete the repair(s) at no cost to you.

TO MAINTAIN SATISFACTION WITH YOUR PURCHASE, IT IS IMPORTANT TO HAVE THIS SAFETY UPDATE COMPLETED.

If you need assistance:

Your CFMOTO dealer is in the best position to answer all your service questions. If you have questions your dealer is unable to address, you can call CFMOTO Customer Care at: 1-888-8CFMOTO or 763-398-2695. If you need assistance contacting or locating a CFMOTO Dealer, please call 1-888-8CFMOTO or visit the CFMOTO web site at <https://cfmotousa.com/find-a-dealer/>.

If you no longer own this vehicle:

This repair notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if the contact information is incorrect, please contact your local CFMOTO dealer to complete a transfer of ownership or have them update the ownership information for you.

We apologize for this inconvenience, and assure you that CFMOTO remains committed to total customer satisfaction and providing high quality products for purchase by powersports enthusiasts around the world.

Sincerely,

CFMOTO Powersports, Inc.