

SAFETY RECALL NOTICE

PLEASE READ IMMEDIATELY

October 3, 2018

Dear CFORCE ATV Owner:

CFMOTO Powersports Inc. has issued an important **Safety Bulletin SAF-2018-01** for certain Model and Year *CFORCE* ATVs, which relates to the addition of a cylinder bracket kit. Our records indicate you that you own an affected vehicle.

The reason for this Notice:

CFMOTO has determined a hazard may exist during extreme engine loading on certain 2016-2018 CFORCE 400, 2017-2018 CFORCE 500 S, and 2017-2018 CFORCE 500 HO ATVs. During extreme engine torque, such as an attempt to pull an overweight load or an ATV that is stuck and cannot move, rapid engine acceleration and the torque applied produces a large swing amplitude of the engine cylinder head.

While CFMOTO is not aware of any circumstances where this has occurred, it is possible the fuel injector high-pressure hose connector could contact the left frame rail, potentially creating a hazardous condition or safety concern if the components were to become damaged and fail. You are being contacted because the Vehicle Identification Number (VIN) registered to you is listed in our warranty database as requiring this update.

If Safety Bulletin SAF-2018-01 has not been performed on your CFORCE ATV, CFMOTO recommends having a cylinder bracket kit installed at your earliest convenience, at no cost to you.

<u>Affected Component(s)</u>	<u>Repair Action(s)</u>
Cylinder Bracket Kit Required	1- Install Cylinder Bracket Kit PN 9GQ0-0300B0 if you own a CFORCE 400 ATV. 2- Install Cylinder Bracket Kit PN 9GQ0-0300D0 if you own a CFORCE 500 S ATV. 3- Install Cylinder Bracket Kit PN 9GQ0-0300E0 if you own a CFORCE 500 HO ATV.

What you should do:

Please contact an authorized CFMOTO dealer at your earliest convenience to have a cylinder bracket kit installed. While talking with your dealer, discuss parts availability, their schedule, and how long they will need to keep your vehicle to complete the repair.

(NOTE: Per CFMOTO warranty terms and conditions, there is no consumer reimbursement policy for return of product to the dealership or for the extension of warranty.)

What CFMOTO and your Dealer will do:

Your CFMOTO dealer has been authorized and is ready to complete the repair(s) at no cost to you. CFMOTO has been working with our suppliers to ensure parts are available.

TO MAINTAIN SATISFACTION WITH YOUR PURCHASE, IT IS IMPORTANT TO HAVE THIS SAFETY UPDATE COMPLETED.

If you need assistance:

Your CFMOTO dealer is in the best position to answer all your service questions. If you have questions your dealer is unable to address, you can call CFMOTO Customer Care at: 1-888-8CFMOTO or 763-398-2695. If you need assistance contacting or locating a CFMOTO Dealer, please call 1-888-8CFMOTO or visit the CFMOTO web site at <https://cfmotousa.com/find-a-dealer/>.

If you no longer own this vehicle:

This repair notice was mailed to you according to our most current registration information. If you no longer own this vehicle, or if the contact information is incorrect, please contact your local CFMOTO dealer to complete a transfer of ownership or have them update the ownership information for you.

We apologize for this inconvenience, and assure you that CFMOTO remains committed to total customer satisfaction and providing high quality products for purchase by powersports enthusiasts around the world.

Sincerely,

CFMOTO Powersports, Inc.